

Generated On: June 26, 2017

You can view our catalogs online at www.kkmfg.com

107Chassis - Body Panels - Pg. 1

| | | |
|---------------|--|---------|
| 107-620-00-04 | Panel, Cowl, Front | 4350.00 |
| 107-620-03-16 | Reinforcement Cowl, Front | 900.00 |
| 107-620-03-72 | Support, Radiator | 533.00 |
| 107-620-03-74 | Reinforcement Cowl, Front | 1090.00 |
| 107-620-07-36 | Baffle, Radiator, Left | 142.56 |
| 107-620-08-36 | Baffle, Radiator, Right | 123.26 |
| 107-620-19-16 | Reinforcement, Firewall | 1000.00 |
| 107-620-50-61 | Wheelhouse, Right: Original | 593.55 |
| 107-620-53-61 | Wheelhouse, Left: Original | 1089.00 |
| 107-626-01-83 | Strut, Wheelhousing Reinforcement, Left | 364.00 |
| 107-626-02-83 | Strut, Wheelhousing Reinforcement, Right | 395.70 |
| 107-628-01-28 | Reinforcement, Pillar, Inner, Left | 416.21 |
| 107-628-02-28 | Reinforcement, Pillar, Inner, Right | 416.65 |
| 107-630-02-69 | Wheelhouse Assembly, Right (SL) | 465.18 |
| 107-630-03-21 | Fender, Rear, Left (SL) | 1200.00 |
| 107-630-04-21 | Fender, Rear, Right (SL) | 1200.00 |
| 107-630-05-21 | Fender, Rear, Left (SLC) | 1140.00 |
| 107-630-06-69 | Wheelhouse Assembly, Right (SLC) | 618.99 |
| 107-630-07-69 | Wheelhouse Assembly, Left (SL) | 573.97 |
| 107-630-08-21 | Fender, Rear, Right (SLC) | 1140.00 |
| 107-630-09-69 | Wheelhouse Assembly, Left (SLC) | 480.34 |
| 107-630-11 | Patch Panel, Lower Front Left | 64.21 |

| | | |
|----------------|------------------------------------|---------|
| 107-630-11-10 | Pillar, Outer, Left | 356.86 |
| 107-630-12 | Patch Panel, Lower Front Right | 64.21 |
| 107-630-12-10 | Pillar, Outer, Right | 356.86 |
| 107-630-13 | Patch Panel, Lower Front, SLC | 123.50 |
| 107-630-14 | Patch Panel, Lower Front, SLC | 123.50 |
| 107-637-00-13 | Washer, Jack Hole | 9.30 |
| 107-637-01-35 | Rocker Panel, Left (SL) | 577.00 |
| 107-637-02-35 | Rocker Panel, Right (SL) | 577.00 |
| 107-637-01-35R | Reproduction Rocker Panel, Left | 375.00 |
| 107-637-02-35R | Reproduction Rocker Panel, Right | 375.00 |
| 107-637-02-76 | Wheelhouse, Outer, Right | 453.75 |
| 107-637-03-35 | Rocker Panel, Left (SLC) | 570.00 |
| 107-637-03-76 | Wheelhouse, Outer, Left | 453.75 |
| 107-637-04-35 | Rocker Panel, Right (SLC) | 570.00 |
| 107-637-05-80 | Filler Panel, Left | 31.95 |
| 107-637-06-80 | Filler Panel, Right | 31.95 |
| 107-640-03-71 | Tail Panel | 755.00 |
| 107-647-00-01 | Cowl, Panel, Rear (SL) | 515.00 |
| 107-720-11 | Door Patch, Bottom Full | 78.40 |
| 107-720-12 | Door Patch, Bottom End Only | 30.00 |
| 107-750-02-75 | Deck Lid, SLC | 4500.00 |
| 107-750-18-75 | Deck Lid, SL | 715.11 |
| 107-758-04-58 | Trunk Star, 3-Hole Mount | 22.69 |
| 107-880-10-18 | Fender, Front, Right: Original | 910.00 |
| 107-880-10-18R | Fender, Front, Right: Reproduction | 370.44 |
| 107-880-11 | Patch Panel, Front Fender, Left | 102.90 |
| 107-880-12 | Patch Panel, Front Fender, Right | 102.90 |
| 107-880-13-18 | Fender, Front, Left: Original | 895.00 |
| 107-880-13-18R | Fender, Front, Left: Reproduction | 370.44 |
| 107-880-14-57 | Hood | 3000.00 |

| | | |
|---------------|------------------------------|--------|
| 107-884-01-35 | Shield, Dirt, Left | 63.50 |
| 107-884-02-35 | Shield, Dirt, Right | 72.00 |
| 107-888-02-38 | Undershield, Plastic | 348.00 |
| 110-884-00-98 | Seal, Dirt Shield | 7.15 |
| 26511-L | Wheelhouse, Patch, Left | 64.83 |
| 26511-R | Wheelhouse, Patch, Right | 64.83 |
| 26551-L | Patch Panel, 1/4 Full, Left | 90.00 |
| 26551-R | Patch Panel, 1/4 Full, Right | 90.00 |
| 26551-LF | Patch Panel, Quarter, Left | 138.65 |
| 26551-RF | Patch Panel, Quarter, Right | 138.65 |

107Chassis - Frame and Floors - Pg. 2

| | | |
|---------------|---|---------|
| 107-610-00-14 | Crossmember, Inner, Rear, Up to # 021129 (SL), Up to # 007822 (SLC) | 254.00 |
| 107-610-00-20 | Crossmember, Behind Seat, Rear Half | 375.00 |
| 107-610-00-31 | Tube, Jackport, SL (4) | 10.00 |
| 107-610-00-32 | Tow Hook W/ Brk | 480.00 |
| 107-610-01-10 | Rail, Frame, Rear Side, Left (SL) | 2020.00 |
| 107-610-01-14 | Crossmember, From # 015082 (SL), From # 004128 (SLC) | 230.51 |
| 107-610-01-75 | Floor, Trunk Assembly | 785.00 |
| 107-610-02-10 | Rail, Frame, Rear Side, Right (SL) | 1690.00 |
| 107-610-02-14 | Crossmember, Inner, Rear, From # 021130 (SL), From # 007823 (SLC) | 363.00 |
| 107-610-02-17 | Crossmember | 250.00 |
| 107-610-03-09 | Rail, Frame, Side Center, Left (SLC) | 845.00 |
| 107-610-03-31 | Jackport, Right Front and Both Rear SLC ONLY | 82.60 |
| 107-610-04-09 | Rail, Frame, Side Center, Right (SLC) | 845.00 |
| 107-610-05-10 | Rail, Frame, Rear Side, Left (SLC) | 1590.00 |
| 107-610-05-31 | Jackport, Front, Left SLC ONLY | 107.10 |
| 107-610-06-10 | Rail, Frame, Rear Side, Right (SLC) | 333.88 |

| | | |
|-----------------|---|--------|
| 107-610-07-09 | Rail, Frame, Side Center, Left (SL) | 787.75 |
| 107-610-07-09R | Rail, Frame, Side Center, Left (SL), Reproduction | 375.00 |
| 107-610-08-09 | Rail, Frame, Side Center, Right (SL) | 787.75 |
| 107-610-08-09R | Rail, Frame, Side Center, Right (SL), Reproduction | 375.00 |
| 107-610-17-61 | Floor, Trunk, Outer, Left | 200.00 |
| 107-610-17-61R | Floor, Trunk, Outer, Left, Reproduction | 88.50 |
| 107-610-18-61 | Floor, Trunk, Up to # 021761 (SL), Up to # 008202 (SLC) | 388.45 |
| 107-610-18-61R | Repro Trunk Floor Up to #021761(SL) #008202(SLC) | 228.00 |
| 107-610-20-61 | Floor, Trunk, From # 021762 (SL), From # 008203 (SLC) | 722.40 |
| 107-610-20-61R | Repro Trunk Floor From #021762(SL) #008203(SLC) | 250.00 |
| 107-611-01-22 | Reinforcement, Frame to Floor, Left | 117.95 |
| 107-611-01-22R | Reinforcement, Frame to Floor, Left, Reproduction | 65.00 |
| 107-611-02-22 | Reinforcement, Frame to Floor, Right | 130.68 |
| 107-611-02-22R | Reinforcement, Frame to Floor, Right, Reproduction | 65.00 |
| 107-611-06-22 | Reinforcement, Frame to Floor, Late | 108.90 |
| 107-611-06-22R | Reinforcement, Frame to Floor, Late, Reproduction | 65.00 |
| 107-612-00-24 | Hanger, Exhaust | 148.50 |
| 107-612-00-74 | Crossmember, Behind Seat, Front Half | 94.00 |
| 107-612-02-14 | Crossmember, Floor, Right | 140.25 |
| 107-612-02-18 | Crossmember, Up to # 015081 (SL), Up to # 004127 (SLC) | 154.28 |
| 107-612-03-14 | Crossmember, Floor, Left | 125.25 |
| 107-612-06-14 | Crossmember, Floor, Late | 95.90 |
| 107-616-01-67 | Floor, Front, Left (ALL) | 357.55 |
| 107-616-01-67RR | Rear Left Floor | 123.75 |
| 107-616-02-42 | Floor, Trunk | 86.21 |
| 107-616-02-42R | Floor, Trunk | 58.50 |
| 107-616-02-67F | Floor, Front, Right (Partial), early without bump | 123.75 |
| 107-616-03-20 | Mount, Acc Pedal | 16.75 |
| 107-616-09-67 | Floor, Rear, Left (SLC) | 163.35 |
| 107-616-10-67 | Floor, Rear, Right (SLC) | 163.35 |

| | | |
|-----------------|---|--------|
| 107-616-18-57 | Floor, Front, Right (ALL) | CALL |
| 107-616-18-67 | Floor Panel, Right | 345.00 |
| 107-616-18-67RR | Rear Right Floor | 123.75 |
| 107-616-01-67F | Floor, Front, Left (Partial) | 123.75 |
| 107-616-18-67F | Floor, Front, Right (Partial), late with bump | 123.75 |
| 107-620-04-14 | Bracket, Battery Tray | 33.99 |
| 107-620-06-86 | Crossmember, Front Bumper, Inner | 344.85 |
| 107-620-07-01 | Firewall, Repair, Left (9in) | 58.65 |
| 107-620-08-01 | Firewall, Repair, Right (10in) | 58.65 |
| 107-620-08-18 | Battery Tray | 134.00 |
| 107-620-09-67 | Crossmember, Front Bumper, Outer | 414.60 |
| 107-626-06-12 | Bracket, Battery Hold Down | 27.22 |
| 124-997-04-86 | Plug, Rear Rail | 8.68 |

107Chassis - Front Bumpers - Pg. 3

| | | |
|---------------|---------------------------------------|--------|
| 107-880-01-14 | Shock Absorber, Left | 217.94 |
| 107-880-01-55 | Guard, Bumper Front, Left | 265.01 |
| 107-880-01-97 | Body to Valences Ect. | 92.56 |
| 107-880-02-14 | Shock Absorber, Right | 209.00 |
| 107-880-02-55 | Guard, Bumper Front, Right | 265.00 |
| 107-880-03-40 | Cover, Between Bumper and Body, Left | 165.00 |
| 107-880-03-97 | Bolt Kit, Bumper Moulding | 152.00 |
| 107-880-04-40 | Cover, Between Bumper and Body, Right | 165.00 |
| 107-880-07-14 | Bracket, Bumper End Mounting | 109.00 |
| 107-880-07-44 | Cover, Bumper to Body | 143.39 |
| 107-880-07-55 | Guard, Front, Left | 219.60 |
| 107-880-08-14 | Bracket, Bumper End Mounting | 116.16 |
| 107-880-08-55 | Guard, Front, Right | 219.60 |

| | | |
|----------------|--|---------|
| 107-880-11-19 | Reinforcement, Bumper, Left, All European and 450SL, Up to Serial # | 510.00 |
| --- | 005793 | |
| 107-880-12-19 | Reinforcement, Bumper, Right, All European and 450SL, Up to Serial # | 510.00 |
| --- | 005793 | |
| 107-880-13-19 | Reinforcement Inner Bumper | 500.00 |
| 107-880-14-19 | Reinforcement Inner Bumper | 609.84 |
| 107-880-15-70 | Bumper End, Left | 276.00 |
| 107-880-16-70 | Bumper End, Right | 264.00 |
| 107-880-19-70 | Bumpr, Center | 1320.00 |
| 107-881-01-63 | Valence, Bumper | 130.68 |
| 107-881-05-01 | Valence, Front Fender Lower, Left | 42.00 |
| 107-881-06-01 | Valence, Front Fender Lower, Right | 42.00 |
| 107-881-06-04 | Valence, Front Fender Lower, Right | CALL |
| 107-884-05-48 | Cover, Above Crossmember | 16.55 |
| 107-885-00-20 | Mount, Absorber to Inner Bracket | 5.89 |
| 107-885-00-42 | Clamp, Bumper End Mounting | 63.00 |
| 107-885-00-74 | Ornamental Bumper Cover | 870.00 |
| 107-885-00-74R | Repro Ornamental Bumper Cover | 700.00 |
| 107-885-03-23 | Cover, Bumper Joint, Front | 103.50 |
| 107-885-05-01 | Bumper, Front, Left | 900.00 |
| 107-885-06-01 | Bumper, Front, Right | 900.00 |
| 107-885-07-40 | Bracket, Inner, Left | 71.69 |
| 107-885-08-40 | Bracket, Inner, Right | 71.69 |
| 107-885-09-21 | Buffer, Rubber Insert to Bumper, Left | 75.00 |
| 107-885-10-21 | Buffer, Rubber Insert to Bumper, Right | 75.00 |
| 107-885-11-97 | Pad, Bumper End Mounting | 11.25 |
| 107-885-13-21 | Rail, Filler to Body | 10.15 |
| 107-885-13-40 | Bracket, Outer, Left | 72.60 |
| 107-885-14-40 | Bracket, Outer, Right | 86.21 |
| 108-990-03-40 | Washer, Shock to Frame | 1.42 |

| | | |
|---------------|--|--------|
| 115-885-01-96 | Buffer, Guard, Front | 102.10 |
| 116-880-05-61 | Bracket, Absorber to Bumper, Left | 119.79 |
| 116-880-06-61 | Bracket, Absorber to Bumper, Right | 80.38 |
| 116-885-00-42 | Clamp, Absorber to Bracket | 26.32 |
| 116-885-03-97 | Pad, Rubber Ornamental Cover to Bumper | 17.24 |
| 116-885-08-21 | Bumper, Rubber Rail, Insert Moulding | 32.70 |
| 003-988-56-78 | Clip to Bumper Joint Front | 0.90 |

107Chassis - Rear Bumpers and Valances - Pg. 4

| | | |
|----------------|-----------------------------------|--------|
| 107-880-05-14 | Shock, Bumper (Takes 2) | 442.00 |
| 107-880-05-55 | Guard, Bumper, Rear | 325.00 |
| 107-880-06-44 | Cover, Bumper to Body Center | 139.75 |
| 107-880-07-19 | Bumper End, Left | 186.95 |
| 107-880-08-19 | Bumper End, Right | 186.95 |
| 107-880-09-14 | Bracket to Bumper | 29.95 |
| 107-880-09-19 | Bumper, Center | 386.60 |
| 107-880-09-44 | Cover, Bumper to Body, End, Left | 83.50 |
| 107-880-10-44 | Cover, Bumper to Body, End, Right | 74.50 |
| 107-880-11-40 | Valance, Outer, Left | 216.60 |
| 107-880-12-40 | Valance, Outer, Right | 210.00 |
| 107-880-15-71 | Bumper End, Left | 214.17 |
| 107-880-16-71 | Bumper End, Right | 214.17 |
| 107-885-00-05 | Face Bar, Center | 600.00 |
| 107-885-01-23 | Cover, Bumper Joint | 136.13 |
| 107-885-01-74 | Cover, Ornamental, Chrome | 885.00 |
| 107-885-01-74R | Cover: Reproduction | 870.00 |
| 107-885-03-05 | Face Bar, Ends, Left | 600.00 |
| 107-885-03-25 | Valance, End, Left | 158.00 |

| | | |
|---------------|----------------------------------|---------|
| 107-885-04-05 | Face Bar, Ends, Right | 600.00 |
| 107-885-04-25 | Valance, End, Right | 158.00 |
| 107-885-05-25 | Valance, Center | 136.00 |
| 107-885-07-05 | Bumper, Center | 1160.00 |
| 107-885-07-21 | Impact Strip Rubber | 360.00 |
| 107-885-09-25 | Valance, Lower | 55.70 |
| 107-885-09-97 | Seal, Ornamental Cover to Bumper | 11.78 |
| 107-885-12-97 | Pad - No Longer Available | 6.90 |
| 107-990-00-44 | Plate, Bracket to Body | 26.32 |
| 115-885-01-96 | Buffer, Guard, Rubber | 102.10 |
| 116-880-05-61 | Bracket, Absorber to Bumper Rear | 119.79 |
| 116-880-07-55 | Guard, Bumper, Left | 62.62 |
| 116-880-07-61 | Bracket, Absorber to Bumper Rear | 119.80 |
| 116-880-08-55 | Guard, Bumper, Right | 62.62 |
| 116-885-00-33 | Cap, To Shock | 4.80 |
| 116-885-00-42 | Clamp, Absorber to Bracket | 26.32 |
| 116-885-02-97 | Rear Bumper Shock Pad | 12.35 |
| 116-885-08-21 | Rail, Impact Strip Center | 32.70 |

107Chassis - Brakelines and Booster - Pg. 5

| | | |
|---------------|---|--------|
| 000-428-06-73 | Lock, Line to Hose | 1.80 |
| 000-428-42-24 | Distributor to Junction at Rear Brake Lines | 26.50 |
| 000-428-67-35 | Hose, Front Brakes | 17.00 |
| 000-430-27-60 | Repair Kit, To Master Cylinder | 141.60 |
| 000-431-09-35 | Cap, Reservoir | 6.30 |
| 000-431-43-34 | Strainer, To Reservoir | 6.75 |
| 000-431-43-87 | Boot, Booster Shaft | 26.35 |
| 000-431-54-33 | Cap, To Reservoir | 7.65 |

| | | |
|---------------|--|--------|
| 000-982-89-78 | Clip, Break Lines to Body | 0.49 |
| 000-997-29-40 | Seal, Reservoir | 2.80 |
| 001-431-42-02 | Reservoir, To Master Cylinder | 155.00 |
| 001-431-53-02 | Master Cylinder Reservoir | CALL |
| 001-431-55-02 | Reservoir, To Cylinder | 75.32 |
| 002-430-28-01 | Master Cylinder, Teves | 198.00 |
| 002-430-68-30 | Booster | 812.00 |
| 002-430-93-01 | Master Cylinder, Bendix | 283.00 |
| 003-430-59-01 | Master Cylinder, Up to Ser 044009 (SL), Up to Ser 020046 (SLC) | 146.72 |
| 004-430-09-01 | Master Cylinder, From Ser 044010 (SL), From Ser 020047 (SLC) | 135.00 |
| 108-995-05-20 | Clamp, Break Line to Body | 0.89 |
| 115-431-01-80 | Gasket, Booster to Body | 2.07 |
| 115-995-01-01 | Clamp, Break Lines to Body | 3.60 |
| 120-420-02-27 | Bolt, Distributor to Floor | 4.60 |
| 123-420-38-28 | Line, Cylinder to Left Front Hose | 5.19 |
| 123-420-50-28 | Line, Rear Hoses to Caliper, Left and Right | 5.39 |
| 123-420-53-28 | Line, Distributor to Left Rear Hose | 5.28 |
| 123-420-54-28 | Line, Cylinder to Left Front Hose | 36.30 |
| 123-420-54-28 | Line, Distributor to Left Rear Hose | 36.30 |
| 123-420-65-28 | Line, To Right Rear Hose, 107 | 19.99 |
| 123-420-65-28 | Line, to Right Rear Hose, 107 | 19.99 |
| 123-420-72-28 | Line, Cylinder to Right Front Hose | 45.40 |
| 123-420-82-28 | Line, Cylinder to Rear Distributor | 47.20 |
| 123-420-84-28 | Line, Cylinder to Rear Distributor | 19.70 |
| 123-420-87-28 | Line, Cylinder to Rear Distributor | 25.01 |
| 123-420-96-28 | Line, To Right Rear Hose, 107 | 47.19 |
| 126-428-01-35 | Hose Rear, Up to Chassis Ser 044-011288, 024 and Ser 001936 | 21.56 |
| 126-428-03-35 | Hose, Rear, Late, Left and Right | 16.60 |

107Chassis - Brake Pedal and Cables - 6

| | | |
|---------------|--|--------|
| 000-300-01-41 | Switch, Transmission Kick Down | 61.25 |
| 000-545-87-09 | Switch, Stop Light | 43.60 |
| 001434-008070 | Pin, Cable Anchor Bracket | 0.84 |
| 107-420-14-85 | Cable, Parking Brake, Up to # 014395 (SLC), Up to # 034128 (SL) | 94.00 |
| 107-420-20-85 | Cable, Brake | 94.00 |
| 107-420-21-85 | Cable, Parking Brake, From # 014396 (SLC), From # 034129 (SL) | 101.64 |
| 107-427-00-82 | Pad, Parking Brake Pedal | 8.35 |
| 107-427-15-41 | Rod, Emergency Brake | 3.10 |
| 107-993-03-10 | Spring, Parking Brake Return | 12.90 |
| 107-993-04-10 | Spring, Pedal Return | 6.90 |
| 107-997-25-81 | Bellows, Accelerator Rod | 11.62 |
| 109-300-18-15 | Rod, Accelerator | 22.84 |
| 115-427-06-71 | Screw, Cable Bracket to Anchor Cable | 3.20 |
| 115-427-09-74 | Pin, Brake Cable, End | 55.27 |
| 115-993-03-25 | Spring, Clip, Brake Cable | 6.90 |
| 115-993-27-10 | Spring, Brake | 26.28 |
| 123-291-00-82 | Pad, Brake Pedal | 15.25 |
| 123-300-02-04 | Pedal, Accelerator, From # 005557 (SL) | 19.97 |
| 123-301-00-22 | Joint, Bracket | 1.70 |
| 123-301-00-82 | Pad, Accelerator, Late Only, From # 050599 (SL), From # 023728 (SLC) | 14.00 |
| 186-993-18-10 | Spring, To Accelerator Linkage Bracket | 37.10 |

107Chassis - Brakes, Front and Rear - Pg. 7

| | | |
|---------------|---------------------------------|-------|
| 000-420-17-55 | Screw, Bleeder to Front Caliper | 16.50 |
| 000-420-19-55 | Screw, Bleeder | 8.50 |
| 000-421-08-87 | Bleeder Screw Cap | 2.75 |

| | | |
|---------------|--|--------|
| 000-421-35-83 | Piston, Caliper Front | 100.00 |
| 000-423-17-74 | Pin, Brake Pad Caliper Rear, Girling | 5.70 |
| 000-586-74-42 | Repair Kit, Front Caliper, From # 009730 | 66.00 |
| 000-990-72-12 | Stud, Disc Front | 3.15 |
| 000-991-03-60 | Pin, Brake Pad Caliper Rear, Teves | 10.89 |
| 000-991-12-60 | Pin, Brake Pad Caliper Front, Up to # 009729 | 2.52 |
| 000-991-17-60 | Pin, Brake Pad Caliper Front, From # 009730 | 3.22 |
| 000-991-26-60 | Pin, Brake Pad Caliper Rear, Bendix | 35.00 |
| 001-420-06-20 | Pads, Rear | 38.50 |
| 001-420-77-20 | Pads, Front (Early, no sensor) | 34.25 |
| 001-420-78-20 | Pads, Front (Thin pad) | 48.01 |
| 001-420-85-20 | Pads, Front (560SL only) | 67.20 |
| 001-420-94-20 | Pads, Front (Large pad) | CALL |
| 001-420-99-20 | Pads, Front (Large pad 1980+) | 41.00 |
| 002-586-44-42 | Repair Kit, Front Caliper, Up to # 009729 | 50.00 |
| 002-586-44-42 | Repair Kit, Rear Caliper | 50.00 |
| 107-420-00-83 | Caliper, Front, Right, From # 062585 | 425.00 |
| 107-420-01-83 | Caliper, Front, Left, From # 062485 | 425.00 |
| 107-420-02-83 | Caliper, Front, Right, Up to # 062584 | 425.00 |
| 107-420-03-83 | Caliper, Front, Left, Up to # 062584 | 425.00 |
| 108-423-00-92 | Spring, To Brakshoe | 2.75 |
| 108-423-01-92 | Spring, Retainer Brake Shoes Rear (2) Sub to 901-993-13-10 | 2.80 |
| 108-423-06-62 | Spring, Retainer Brake Shoes | CALL |
| 108-423-06-92 | Spring, Retainer Brake Shoes | 5.25 |
| 115-423-02-73 | Lock Plate, Caliper Rear | 5.30 |
| 115-994-07-32 | Lock Plate to Caliper Front | 7.67 |
| 116-420-02-05 | Disc, Front, From # 062585 | 60.00 |
| 116-423-00-50 | Sleeves, To Breakshoe | 5.75 |
| 123-420-00-73 | Screw, to Brake Shoes Rear | 8.25 |
| 123-420-05-83 | Caliper, Rear, Left | 175.00 |

| | | |
|---------------|-----------------------------------|--------|
| 123-420-06-83 | Caliper, Rear, Right | 175.00 |
| 123-421-01-71 | Screws, Caliper Front | 5.50 |
| 123-423-00-71 | Screw, To Rear Caliper Lock Plate | 6.00 |
| 126-420-00-05 | Disc, Front, Up to # 062584 | 48.06 |
| 126-420-01-20 | Shoes, Brake Rear | 47.50 |
| 126-423-00-12 | Disc, Rear | 41.16 |

107Chassis - Chrome Trim and Emblems I - Pg. 8

| | | |
|----------------|---|--------|
| 000-988-10-81 | Clip, Moulding | 1.40 |
| 000-988-15-81 | Plug, Moulding, In Body All Except Rocker | 1.81 |
| 000-988-55-81 | Plug, In Body SLC (Takes 16) | 1.40 |
| 000-988-75-81 | Clip, Rocker Moulding (Takes 14) | 0.90 |
| 000-988-76-81 | Plug, In Body SL (Takes 14) | 2.40 |
| 000-988-77-81 | Clip, Moulding | 1.60 |
| 000-990-47-33 | Rear Quarter Moulding T-Bolt (Takes 2) | 1.80 |
| 000-990-46-33 | Fender Moulding T-Bolt (Takes 4) | 1.80 |
| 107-586-00-80 | Moulding, Wheel: (Short Version) (Set of 4) | 121.00 |
| 107-586-00-80L | Moulding, Wheel: (Long Version On Request) (Set of 4) | 111.75 |
| 107-690-09-80 | Moulding, Quarter, Left: 450SL/380SL | 92.60 |
| 107-690-10-80 | Moulding, Quarter, Right: 450SL/380SL | 92.60 |
| 107-690-11-80 | Moulding, Quarter, Left: 450SLC/380SLC | 192.40 |
| 107-690-12-80 | Moulding, Quarter, Right: 450SLC/380SLC | 192.40 |
| 107-690-13-80 | Moulding, Tail Panel, End, Left | 520.00 |
| 107-690-14-80 | Moulding, Tail Panel, End, Right | 520.00 |
| 107-690-24-80 | Moulding, Tail Panel Upper, Center | 815.00 |
| 107-698-01-21 | Gasket Moulding, Left: 450SL/380SL | 37.25 |
| 107-698-01-80 | Moulding, Rocker, Left: 450SL/380SL, \$48.40 | 223.25 |
| --- | Moulding | |

| | | |
|---------------|---|--------|
| 107-698-02-80 | Moulding, Rocker, Right: 450SL/380SL | 375.00 |
| 107-698-03-21 | Gasket Moulding, Left: 450SLC/380SLC | 49.05 |
| 107-698-04-21 | Gasket Moulding, Right: 450SLC/380SLC | 49.05 |
| 107-698-05-80 | Moulding, Rocker, Left: 450SLC/380SLC | 79.90 |
| 107-698-06-80 | Moulding, Rocker, Right: 450SLC/380SLC | 79.90 |
| 107-720-01-80 | Moulding, Door Includes Gasket, Left | 206.95 |
| 107-720-02-80 | Moulding, Door Includes Gasket, Right | 206.95 |
| 107-728-01-30 | Moulding, Top Edge of Door, Left | 192.39 |
| 107-728-02-30 | Moulding, Top Edge of Door, Right | 192.39 |
| 107-760-03-59 | Handle, Door Outside, Left, Up to # 051355 (SL), Up to # 04229 (SLC) | 515.00 |
| 107-760-04-59 | Handle, Door Outside, Right, Up to # 051355 (SL), Up to # 04229 (SLC) | 515.00 |
| 107-760-07-59 | Handle, Door Outside, Left, From # 04230 (SL), From # 051356 (SLC) | 515.00 |
| 107-760-08-59 | Handle, Door Outside, Right, From # 04230 (SL), From # 051356 (SLC) | 515.00 |
| 107-810-30-16 | Mirror, Outside, Glass Only, Right, From # 029705 (SL), From # 011996 (SLC) | 430.00 |
| --- | | |
| 107-811-05-22 | Mirror, Outside, Glass Only, Left, Up to # 011995 (SL), Up to # 029704 (SLC) | 88.02 |
| --- | | |
| 107-811-06-22 | Mirror, Outside, Glass Only, Right, Up to # 001995 (SL), Up to # 029704 (SLC) | 78.95 |
| --- | | |
| 107-880-01-82 | Moulding, Fender Includes Gasket, Left | 118.00 |
| 107-880-02-82 | Moulding, Fender Includes Gasket, Right | 118.00 |
| 107-881-01-32 | Moulding, Over Headlamp, Left | 57.20 |
| 107-881-02-32 | Moulding, Over Headlamp, Right | 66.00 |
| 115-401-03-24 | Cover, Wheel | 413.82 |
| 123-401-01-28 | Clip, Wheel Cover | 4.60 |

107Chassis - Chrome Trim and Emblems II - Pg. 9

| | | |
|---------------|---|--------|
| 000-471-61-30 | Cap, Gas, Locking, From # 004970, From # 008202 (SLC) | 112.55 |
|---------------|---|--------|

| | | |
|----------------|--|--------|
| 000-824-13-27 | Insert, Wiper Blade (Must have blade length before ordering) | 11.60 |
| 107-693-01-35 | Cover, Latch, Left | 245.28 |
| 107-693-02-35 | Cover, Latch, Right | 239.80 |
| 107-698-00-97 | Gasket, Rear Mouldings | 38.00 |
| 107-750-12-85 | Lock, Trunk | 134.35 |
| 107-758-00-58 | Trunk Star (SLC) | 83.60 |
| 107-758-01-58 | Trunk Star (SL) | 90.75 |
| 107-758-02-02 | Handle, Trunk | 246.00 |
| 107-758-04-58 | Trunk Star, 3-hole mount | 22.69 |
| 107-817-00-15 | Emblem (280SL) | CALL |
| 107-817-01-15 | Emblem (350SL) | 75.00 |
| 107-817-02-15 | Emblem (450SL) | 71.70 |
| 107-817-05-15 | Emblem (450SLC) | 75.00 |
| 107-817-08-15 | Emblem (380SL) | 75.00 |
| 107-817-14-15 | Emblem (560SL) | 28.13 |
| 107-820-03-45 | Wiper Blade | 150.65 |
| 107-820-39-44 | Wiper Arm, Left | 334.00 |
| 107-820-40-44 | Wiper Arm, Right | 334.00 |
| 107-869-00-19 | Washer Nozzle on Bottle | 29.00 |
| 107-860-01-47 | Washer Nozzle on Hood | 20.90 |
| 107-880-02-97 | Mounting, Kit, With Bolts, Screws and Washers | 49.00 |
| 107-880-03-86 | Star, Grille With Barrel | 400.40 |
| 107-888-02-15 | Grille Surround: Original | 474.00 |
| 107-888-02-15R | Grille Surround: Reproduction | 187.00 |
| 107-888-03-21 | Grille Wing, Left | 223.25 |
| 107-888-04-21 | Grille Wing, Right | 223.25 |
| 107-888-11-23 | European Style, Left | 48.00 |
| 107-888-12-23 | European Style, Right | 56.00 |
| 107-888-13-23 | Without Bumper Shock, Left | 81.40 |
| 107-888-14-23 | Without Bumper Shock, Right | 88.00 |

| | | |
|---------------|--|-------|
| 107-888-15-23 | Grille Screen, Left | 82.00 |
| 107-888-16-23 | Grille Screen, Right | 82.00 |
| 107-888-19-23 | With Bumper Shock, Left | 50.82 |
| 107-888-20-23 | With Bumper Shock, Right | 59.89 |
| 124-470-00-05 | Cap, Gas, Plain, Up to # 004969 (SL), Up to # 008203 (SLC) | 25.00 |
| 901-817-03-16 | Emblem, Hood | 29.05 |

107Chassis - Heating and Cooling - Pg. 10

| | | |
|---------------|---|---------|
| 000-500-43-93 | Fan Assembly - 1973 ONLY | 785.00 |
| 000-500-60-93 | Fan Assembly, Electric, Auxillary | 450.00 |
| 000-503-07-01 | Grille, Cover Over Fan | 6.55 |
| 001-987-24-51 | Seal, Air Screen to Body | 29.04 |
| 001-987-26-51 | Seal, Air Intake Grille | 10.35 |
| 107-500-01-49 | Reservoir, Engine Coolant, SL | 254.00 |
| 107-500-04-49 | Reservoir, Engine Coolant, SLC | 184.00 |
| 107-501-00-82 | Hose, Lower | 28.56 |
| 107-501-09-01 | Radiator, Up to Chassis # 004127 (SLC) | 862.06 |
| 107-501-12-01 | Radiator, 450SL ALL, From Chassis # 004128 (SLC) | 876.54 |
| 107-505-02-55 | Fan Shroud for 350SLC, 350SL, 450SLC, 450SL, 380SLC and 350SL | 78.96 |
| 107-505-05-55 | Fan Shroud for 280SLC and 280SL | 65.34 |
| 107-505-06-55 | Fan Shroud for 450SLC, 500SLC, 500SL up to 000986, and 380SL up to 009131 | 121.69 |
| --- | | |
| 107-505-07-55 | Fan Shroud for 380SL from 009131 | 71.69 |
| 107-505-08-55 | Fan Shroud for 300SL | 90.75 |
| 107-820-03-10 | Switch, Heater Blower | 232.00 |
| 107-830-01-08 | Motor, Heater Blower | 1250.00 |
| 107-831-00-98 | Seal, Defroster Duct | 54.45 |
| 107-831-01-42 | Seal, Heater | 5.78 |

| | | |
|---------------|--|--------|
| 107-831-01-94 | Hose, Heater Core, LL | 60.85 |
| 107-831-03-42 | Seal, Air Intake | 11.55 |
| 107-831-07-94 | Hose, Engine at Water Valve | 38.12 |
| 107-831-10-94 | Hose, Heater Core Right | 39.93 |
| 107-832-02-65 | Grille, Air Intake, Right | CALL |
| 107-835-00-06 | Relay, Blower Motor | 655.00 |
| 107-835-00-23 | Seal, Air Damper | 48.10 |
| 107-835-01-20 | Valve, Water | 98.00 |
| 107-835-01-23 | Seal, Blower Motor | 42.30 |
| 107-835-02-01 | Heater Core | CALL |
| 107-836-01-65 | Air Intake Grille, Left | 112.50 |
| 107-836-02-65 | Air Intake Grille, Right | 112.50 |
| 116-180-16-65 | Fan, Cooling | 660.00 |
| 116-200-05-22 | Fan Clutch | 590.00 |
| 116-205-13-06 | Fan Blade | 433.79 |
| 116-501-34-82 | Hose, Upper | 19.88 |
| 116-835-00-20 | Valve, Water | 379.35 |
| 123-501-02-15 | Cap, Reservoir | 19.60 |
| 900271-008019 | Hose, to Reservoir Top, 8X15X2000mm | 30.35 |
| 900271-018036 | Hose, Reservoir Bottom to Radiator, 18X25X1000mm | 23.52 |
| Belts | Click to select the belt(s) you wish to order from our available list. | CALL |

107Chassis - Front Suspension, Steering, Springs - Pg. 11

| | | |
|---------------|----------------------------------|-------|
| 000-330-04-85 | Repair Kit, Drag Link | 8.00 |
| 000-338-50-10 | Ball Joint, Left Hand Threaded | 25.00 |
| 000-338-52-10 | Ball Joint, Right Hand, Threaded | 25.00 |
| 000-463-51-32 | Shock Absorber | 50.50 |

| | | |
|----------------|---|--------|
| 000-981-58-05 | Bearing, Front Inner | 21.50 |
| 000-981-59-05 | Bearing, Front Outer | 28.07 |
| 000-997-47-52 | Hose, Cooling Pipe To Pump 380MM or Hose, Return To Box 250MM | 19.80 |
| 001-990-54-51 | Nut, To Pitman Arm | 6.71 |
| 005-997-50-46 | Seal, Front Caliper | 8.88 |
| 107-320-00-30 | Front Shocks | 98.50 |
| 107-320-02-30 | Front Shocks (560 SL Only) | 150.00 |
| 107-321-02-84 | Buffer, Rubber Front Spring, Top | 12.68 |
| 107-330-00-51 | Repair Kit, Bearings (1985 and After) | 40.00 |
| 107-330-01-03 | Tie Rod | 30.75 |
| 107-330-02-75 | Mount, Subframe (4) | 23.23 |
| 107-330-00-37B | Bilstein, Gas | 99.96 |
| 107-460-06-05 | Drag Link | 33.55 |
| 107-463-10-10 | Arm, Steering Intermediate (Idler) | 95.99 |
| 107-463-16-01 | Pitman Arm | 730.00 |
| 107-997-44-82 | Hose, Pressure | 123.15 |
| 114-321-06-04 | Spring, Front (SL) | 196.05 |
| 114-321-07-04 | Spring, Front (SLC) | 306.07 |
| 114-323-05-85 | Bushing, Sway Bar Mounting, Rubber | 5.88 |
| 114-330-01-85 | Repair Kit, Ball Joint, Lower Arm | 12.96 |
| 114-586-03-33 | Repair Kit, Boot for Ball Joint | 3.75 |
| 115-320-00-47 | Repair Kit, Torsion Bar Front | 50.00 |
| 115-330-00-51 | Repair Kit, Bearings (1984 and Prior) | 56.25 |
| 115-330-16-75 | Repair Kit, Lower | 53.00 |
| 115-330-17-75 | Repair Kit, Upper Control Arm, Inner | 59.00 |
| 115-330-18-75 | Repair Kit, Subframe | 93.22 |
| 115-330-38-07 | Control Arm, Upper, Left | 645.00 |
| 115-330-39-07 | Control Arm, Upper, Right | 645.00 |
| 115-333-02-65 | Buffer, Subframe | 2.54 |
| 115-333-11-27 | Ball Joint, Lower | 39.20 |

| | | |
|----------------------|------------------------------|--------------|
| 126-460-08-19 | Repair Kit, Idler Arm | 23.98 |
|----------------------|------------------------------|--------------|

107Chassis - Rear Suspension and Axle - Pg. 12

| | | |
|-----------------------|---|---------------|
| 107-330-00-37B | Bilstein Shock | 99.96 |
| 107-330-00-37M | Monroe Gas Shock | CALL |
| 107-586-00-32 | Repair Kit, Torsion Bar Rear - Up to #007869 | 29.95 |
| 107-586-04-32 | Repair Kit, Torsion Bar Rear - From #007869 | 8.81 |
| 115-320-03-44 | Bumper, Rear Axle to Frame | 17.80 |
| 115-320-15-89 | Tie Rod, Torsion Bar to Rear Axle | 26.50 |
| 115-324-22-04 | Rear Spring | 148.85 |
| 115-325-22-44 | Rubber Buffer - 9.5MM | 35.39 |
| 115-325-23-44 | Rubber Buffer - 14MM | 35.39 |
| 115-325-24-44 | Rubber Buffer - 19MM | 35.39 |
| 126-320-09-31B | Bilstein Shock | CALL |
| 126-320-09-31M | Monroe Gas Shock | CALL |
| 126-320-09-31 | Bilstein Shock (Rear) | 86.65 |

107Chassis - Filters and Tune-Up Parts - Pg. 13

| | | |
|----------------------|---|---------------|
| 000-092-76-01 | Filter, Fuel, Elec. Fuel Inj. Only | 17.70 |
| 000-094-13-55 | Clip, Air Cleaner, Eng. # 117-985 and # 117-982 | 2.40 |
| 000-156-41-10 | Suppressor, Plug Wire End | 54.45 |
| 000-158-03-19 | Pulse Generator, All 983 Engines and 982 Engines From # 016344 | 935.00 |
| 000-158-09-85 | Cover, Distributor Cap, Eng. # 117-982, Up to # 036325 Only | 126.20 |
| 000-158-23-31 | Rotor, Without Governor | 17.35 |
| 000-158-25-31 | Rotor, With Governor | 61.85 |
| 000-158-26-02 | Cap, Distributor, Push on Type (Before 1974) | 75.75 |

| | | |
|---------------|---|--------|
| 000-158-28-03 | Coil, Ignition | 84.50 |
| 000-158-30-18 | Vacuum Advance, All Engine # 117-982, Eng # 117-985, Up to # 022354 | 159.00 |
| 000-158-34-90 | Points | 31.80 |
| 000-158-42-02 | Cap, Distributor, Screw on Type (Starting At 1974) | 62.25 |
| 000-158-57-18 | Vacuum Advance, Eng. # 117-985, From # 022355 | 69.15 |
| 000-180-06-09 | Filter, Oil with Seal | 8.00 |
| 001-094-22-80 | Seal, Air Cleaner Bottom, Engine # 117-985 | 13.46 |
| 001-094-23-80 | Seal, Air Cleaner Cover, Eng. # 117-985 | 8.35 |
| 001-094-23-80 | Seal, Air Cleaner Cover, Eng. # 117-982 | 8.35 |
| 001-094-25-80 | Seal, Air Cleaner Bottom, Engine # 117-982 | 11.35 |
| 001-094-27-04 | Filter, Air For Eng. # 111-982 | 35.14 |
| 001-094-78-04 | Filter, Air For Eng. # 117-985 | 37.04 |
| 001-997-05-48 | Seal, Distributor to Block | CALL |
| 002-477-17-01 | Fuel Filter (380SL-From 1980) | 26.75 |
| 002-477-19-01 | Filter, Fuel, Up to 1980 | 29.34 |
| 011-997-05-48 | Seal, Distributor Bottom | 2.32 |
| 100-997-08-81 | Grommet, Ignition, Wire Set (Q 2) | 4.00 |
| 116-150-00-18 | Wire Set, Spark Plugs, Push on Type | 131.15 |
| 116-150-01-18 | Wire Set, Spark Plugs, Screw on Style, Starting 1974, Designed for | 142.40 |
| --- | Boshe Plugs Only | |
| 001-156-05-01 | Condenser, With Wire | 92.56 |
| W7-DC | Spark Plugs, Up to 1975 | 4.95 |
| W8-DC | Spark Plugs, 1975 and Up | 4.10 |

107Chassis - Body Lighting - Pg. 14

| | | |
|---------------|-----------------------------|--------|
| 000-820-65-56 | Fog Light Assembly | 635.25 |
| 000-826-04-40 | Reflector, Side Marker Lamp | 31.00 |
| 000-826-55-99 | Headlamp Bulb, Left | 12.95 |

| | | |
|---------------|---|---------|
| 000-826-54-99 | Headlamp Bulb, Right | 13.20 |
| 000-997-03-81 | Grommet, Taillamp | 1.40 |
| 001-544-97-32 | Hazard Flasher (SLC upto 019097) (SL upto 042309) | 172.40 |
| 001-826-20-89 | Rim, HL Bulb Retainer | 185.00 |
| 001-826-61-90 | Left Lens, European | 120.00 |
| 001-826-62-90 | Right Lens, European | 120.00 |
| 001-826-65-90 | Lens, Turn Signal Left (to 015080) | CALL |
| 001-826-66-90 | Lens, Turn Signal Right (to 015080) | CALL |
| 001-826-71-90 | Fog Light Lens (lens only, not full assembly) | 162.00 |
| 001-987-55-46 | Gasket, Turn Signal Lens | 2.54 |
| 002-826-18-90 | Lens, Turn Signal (Square) | 61.70 |
| 072601-012210 | Bulb, Turn Signal | 2.10 |
| 072601-012290 | Bulb, Fog Lights | 5.50 |
| 072601-012130 | Bulb - License, Taillight, Side Ref | 1.80 |
| 072601-012190 | Bulb - Blinker, Stop, Backup | 1.18 |
| 107-820-00-62 | Lamp, License Plate | 126.77 |
| 107-820-03-20 | Turn Signal Assem. (from 015081) | 302.00 |
| 107-820-04-20 | Turn Signal Assem. (from 015081) | 297.66 |
| 107-820-09-66 | Lens | 42.30 |
| 107-820-17-61 | Headlamp Assem. - Euro Left (Man) | 445.20 |
| 107-820-18-61 | Headlamp Assem. - Euro Right (Man) | 381.75 |
| 107-820-27-66 | Lens, Taillamp, Left | 625.00 |
| 107-820-28-66 | Lens, Taillamp, Right | 625.00 |
| 107-820-39-61 | Headlamp Assembly - USA Left | 635.04 |
| 107-820-40-61 | Headlamp Assembly - USA Right | 662.20 |
| 107-820-41-64 | Taillamp Assembly, Left | 1160.00 |
| 107-820-42-64 | Taillamp Assembly, Right | 1160.00 |
| 107-820-47-61 | Headlamp Assem. - Euro Left (Auto) | 800.00 |
| 107-820-48-61 | Headlamp Assem. - Euro Right (Auto) | 800.00 |
| 107-826-01-58 | Seal, Taillamp Lens, Left | 98.01 |

| | | |
|---------------|---|-------|
| 107-826-02-58 | Seal, Taillamp Lens, Right | 98.01 |
| 107-826-03-89 | Lens, Headlamp, Left | 67.20 |
| 107-826-04-89 | Lens, Headlamp, Right | 67.20 |
| 115-990-05-57 | Lamp Attaching Knob | 22.80 |
| 123-820-00-05 | Hazard Flasher (SLC fr 019098) (SL fr 042310) | 59.47 |

107Chassis - Gaskets and Seals - Pg. 15

| | | |
|---------------|--|--------|
| 000-826-77-80 | Seal, Side Marker, Left | 36.30 |
| 000-826-78-80 | Seal, Side Marker, Right | 36.30 |
| 000-826-86-80 | Seal, Lens to Housing | 22.34 |
| 000-987-10-15 | Plug, Attaches Seal to Door (Takes 20) | 2.60 |
| 001-987-26-51 | Seal, Air Intake Grille. (232mm) | 10.35 |
| 001-987-55-46 | Seal, Turn Signal Lens (330mm) | 2.54 |
| 002-988-91-78 | Clip | 1.75 |
| 003-988-23-78 | Clip, Curved End of Outer Seal (2) | 10.00 |
| 107-673-01-65 | Seal, Side Window, Outer, Left (SLC) | 15.70 |
| 107-673-02-24 | Seal, Rear Side Window, Front | 36.30 |
| 107-673-02-65 | Seal, Side Window, Outer, Right (SLC) | 15.70 |
| 107-673-03-65 | Seal, Window Felt, Rear Inner, Left (SLC) | CALL |
| 107-673-04-65 | Seal, Window Felt, Rear Inner, Right (SLC) | 46.28 |
| 107-678-04-20 | Seal, Backglass (SLC) | 156.09 |
| 107-690-07-97 | Seal, Windshield Post, Left (ALL) | 125.00 |
| 107-690-08-97 | Seal, Windshield Post, Right (ALL) | 125.00 |
| 107-720-11-78 | Seal, Top to Door Glass, Left (SLC) | 284.00 |
| 107-720-12-78 | Seal, Top to Door Glass, Right (SLC) | 284.00 |
| 107-720-15-78 | Seal, Door | 350.00 |
| 107-720-16-78 | Seal, Door | 350.00 |
| 107-725-27-65 | Seal, Window, Felt, Inner, Left | 196.90 |

| | | |
|---------------|---------------------------------------|--------|
| 107-725-28-65 | Seal, Window, Felt, Inner, Right | 157.00 |
| 107-758-00-98 | Seal, Trunk (SL) | 188.60 |
| 107-758-02-05 | Gasket, Trunk Handle | 20.00 |
| 107-758-02-98 | Seal, Trunk (SLC) | 372.00 |
| 107-766-01-05 | Gasket, Door Handle (2) | 5.50 |
| 107-811-01-61 | Gasket, Mirror, Left | 30.85 |
| 107-811-02-61 | Gasket, Mirror, Right | 30.85 |
| 107-826-01-58 | Seal, Taillamp Lens, Left | 98.01 |
| 107-826-02-58 | Seal, Taillamp Lens, Right | 98.01 |
| 107-831-03-42 | Seal, Air Intake Flap | 11.55 |
| 107-988-07-78 | Clip, Outer (Takes 20) | 4.80 |
| 107-988-08-78 | Clip, Inner (Takes 2) | 1.40 |
| 107-997-06-86 | Plug, Attaches Seal to Door (Takes 2) | 13.07 |
| 107-997-24-81 | Grommet, Fuel Filler Neck | 7.80 |
| 110-471-01-80 | Gasket, Gas Cap | 6.20 |
| 111-987-15-40 | Bumper, Deck Lid | 2.20 |
| 123-725-02-65 | Seal, Window Felt, Outer | 29.00 |
| 201-988-02-11 | Bumper, Hood Adjustment | 1.60 |

107Chassis - Tops, Seals and Accessories - Pg. 16

| | | |
|---------------|---|--------|
| 002-988-91-78 | Clip, Felt Seal, Side Window | 1.75 |
| 107-720-05-78 | Seal, Hardtop to Door Glass, Left (Hardtop) | 110.75 |
| 107-720-06-78 | Seal, Hardtop to Door Glass, Right (Hardtop) | 110.75 |
| 107-720-09-78 | Seal, Conv. Top to Door Glass, Left (SL) | 52.65 |
| 107-720-10-78 | Seal, Conv. Top to Door Glass, Right (SL) | 52.65 |
| 107-725-05-66 | Seal, Conv. Top to Door Glass, Rear, Left (SL) | 39.95 |
| 107-725-06-66 | Seal, Conv. Top to Door Glass, Rear, Right (SL) | 39.95 |
| 107-758-01-98 | Seal, Top Cover to Body | 155.15 |

| | | |
|---------------|--|---------|
| 107-770-00-66 | Cable, S/T Frame Tension | 11.98 |
| 107-770-03-02 | Frame, Conv. Top Assembly | 7470.00 |
| 107-771-00-98 | Seal, Conv. Top to Body | 79.90 |
| 107-779-00-22 | Seal, Soft Top and Hardtop to Windshield Frame | 30.90 |
| 107-790-01-98 | Seal, Hardtop to Body | 208.75 |
| 201-988-02-11 | Buffer, Hood Stop | 1.60 |
| ME729-G1 | Convertible Top, Original Canvas, Black on Tan | 628.00 |
| ME729-G2 | Convertible Top, Original Canvas, Blue on Tan | 628.00 |
| ME729-G3 | Convertible Top, Original Canvas, Brown on Tan | 628.00 |
| ME729-G4 | Convertible Top, Original Canvas, Tan on Tan | 628.00 |
| 149-4040-PAL | Perforated Vinyl Headliner | 178.20 |

107Chassis - Upholstery, Carpets, Mat and Accessories - Pg. 17

| | | |
|----------------|--|---------|
| 107-680-00-87R | Dash Covering, 3 Colors Available: Black, Brown and Blue | 138.60 |
| 107-680-20-50 | Console, Center, Need Trim Code For Color | 1470.00 |
| 107-682-03-26 | Hood Insulation | 121.61 |
| 107-684-09-05 | Mat, Trunk, Fibrous | 132.50 |
| 107-686-01-80 | Mat, Sill Entrance, Black (Takes 2) | 59.85 |
| 107-686-03-36 | Cover, Sill, Inner, Up to # 035423, Left | 78.05 |
| 107-686-04-36 | Cover, Sill, Inner, Up to # 035423, Right | 78.05 |
| 107-686-07-36 | Sill Trim, Up to # 010806, Left (SLC Only) | 88.42 |
| 107-686-08-36 | Sill Trim, Up to # 010806, Right (SLC Only) | 101.83 |
| 107-860-13-69 | Seatbelt Receiver | 76.90 |
| 107-860-14-69 | Lap Belts | 52.92 |
| 107-860-93-85 | Shoulder Belt (Requires 2) | 321.25 |
| 107-913-03-28 | Cover, Left Seat, Left Upper | 31.80 |
| 107-913-04-28 | Cover, Right Seat, Left Upper | 30.90 |
| 107-913-05-28 | Cover, Right Seat, Right Upper | 30.90 |

| | | |
|------------------------|--|----------------|
| 107-913-06-28 | Cover, Left Seat, Right Upper | 33.60 |
| 107-913-13-28 | Cover, Seat Lower Left (Requires 2) | 30.90 |
| 107-913-14-28 | Cover, Seat Lower Right (Requires 2) | 30.90 |
| 107-914-00-16 | Cushion, Back: Reproduction Excellent Quality | 180.00 |
| 107-914-02-14 | Cushion, Bottom | 180.00 |
| 107-Carpet-1 | Carpet Set, All Colors Multi-Loop or Velour | 616.58 |
| 107-Carpet-Tr | Carpet, Trunk, Multi-Loop or Velour | 365.31 |
| 107-DR-PNL-TEX | Door Panel Kit | CALL |
| 107-RS-LTHR | Seat, Right Rear Kit, SLC | CALL |
| 107-RP-LTHR | Seat Panels, Rear of Front Seat | 156.85 |
| 107-SEAT-COVERS | Seat and Head Rest Covers (Lid cover and arm rest not pictured, but included) | 1157.50 |
| --- | | |

Please note that we cannot guarantee our prices due to fluctuating supply, currency exchange, and cost of materials.